

Occurrence Report

B7642

State reporting	Taiwan Island	Date entered	2012/10/16
Reporting org.	Taiwan (ASC)	Report last modified	2014/7/9 PM 04:33:59
State file number	ASC-AOR-12-07-001	Report status	Data

Headline Landing on wrong runway in Tainan Airport, UNI Air B7642, B-15231, Dash-8-300

Occurrence class	Serious incident	Occurrence category	RI-VAP:Runway incursion - vehicle, a/c or person
Local date	2011/6/28 AM 09:22:00	UTC date	2011/6/28 AM 01:22:00
State/area of occurrence	Taiwan Island	Latitude of occ	22:57 North
Location of occ	RCNN Airport	Longitude of occ	120:13 East

Aircraft Involved

Manufacturer/model	DE HAVILLAND - DHC8-300	Aircraft registration	B-15231
Call sign	GLORY	Operator	Taiwan - Uni Air - (to be coded)
Flight phase	Landing		

TAIWAN ISLAND, ASC-AOR-12-07-001**Filing information**

Headline	Landing on wrong runway in Tainan Airport, UNI Air B7642, B-15231, Dash-8-300		
State reporting	Taiwan Island	Date entered	2012/10/16
State file number	ASC-AOR-12-07-001	Reporting org.	Taiwan (ASC)

When

Local date	2011/6/28 AM 09:22:00	UTC date	2011/6/28 AM 01:22:00
-------------------	-----------------------	-----------------	-----------------------

Where

State/area of occurrence	Taiwan Island	Latitude of occ	22:57 North
Location of occ	RCNN Airport	Longitude of occ	120:13 East

Classification

Occurrence class	Serious incident	Occurrence category	RI-VAP:Runway incursion - vehicle, a/c or person
-------------------------	------------------	----------------------------	--

Severity

Damage aircraft	None	Damage aerodrome	None
Third party damage	No	Injury level	None

Injury totals

	Fatal	Serious	Minor	None	Unknown	Total
Total on ground	0	0	0	0	0	0
Total on aircraft	0	0	0	47	0	47
Grand total	0	0	0	47	0	47

ATM relation

ATM contribution	None	Effect on ATM service	No effect
-------------------------	------	------------------------------	-----------

NARRATIVE

On June 28, 2011, UNI Air flight B7 642,a Dash-8-300 (national registration number B-15231),the aircraft was on a scheduled passenger flight from Makong Airport to Tainan Airport. There were 2 pilots, 2 cabin crewmembers and 43 passengers on board. The aircraft was scheduled to land at the runway 18L at Tainan Airport, however it landed at the non-designated Runway 18R upon arrival. The aircraft had no damage and all people on board were safe. Finding related to probable causes : when the captain had the runway in sight, the aircraft has passed over the visual descent point and was approaching the miss approach point. At that time the captain had to maneuver considerably to land at the landing area due to the aircraft at a higher altitude, and then because of the impact from heavy rain, failing to wear glasses and not turning on wipers, the captain's focus was limited to the landing operation and he did not receive the information about aiming to the wrong runway provided by the controller and the F/O. When realizing that they

NARRATIVE

were aiming the wrong runway, the F/O reminded the captain the aircraft was off course to the right side. When the captain did not respond to the reminder, the F/O did not remind the captain again and did not determine to call out for go-around, which led to the captain not being alerted the runway

he was trying to land was wrong and the aircraft as a result landed at the unassigned runway 18R. The captain and the F/O knew there were 2 parallel runways 18L and 18R at Tainan Airport, however on the day of the occurrence they were not sufficiently alerted to the situation. When visualizing one runway, pilots identified it right away as the runway 18L assigned by the controller without a proper verification. During approach there was medium rainfall near the airport area and there existed different levels of clouds scattered at the altitude below 1,000 ft. and cumulonimbus at the south east side

of the airport near the runway 18L, which influenced the pilots to locate the runway 18L assigned by the controller during the visual approach phase. When the pilot had the visual contact with the runway, the aircraft had approached or entered into the blind zone of the approach lights of runway 18L, which might make the approach lights difficult to be located by the pilots. When the weather permits the pilots should have had an opportunity to locate the runway 18L with the approach lights on if they have had sufficient situation awareness. The VOR/DME approach is non-precision approach, which is

less accurate. After the pilot disengaged auto-pilot at the final approach phase, the aircraft remained positioning at the west side of the extended runway

18R centerline; which led to the aircraft to aim at the runway 18R which was closer to the aircraft instead of the runway 18L assigned by the ATC when the pilot had the visual contact with the runway. Findings related to risks : When the pilot saw the runway, the aircraft was at a slightly higher altitude.

In order to have the aircraft landing at the runway landing area, the throttles were set to idle and the aircraft head downwards, so that a bigger glide path

angle could be achieved. This maneuver caused the air speed temporarily to be lower than the approach speed, the maximum descending rate to be over

1,000 ft/min and the average descending rate to be 775 ft/min, which was more than the normal descending rate of 500 ft/min. The average glide path angle of the aircraft was 6.02° which was also bigger than the normal glide slope angle of 3°. Uni Air's existing procedures related to the non-precision approach define that when the aircraft approaches to the visual descent point without pilot's visual contact with the runway, the aircraft may remain above the minimum descent altitude to proceed approach to the miss approach point. However when the miss approach point is located far behind the visual descent point together with the delay of the pilot's visual contact with the runway, it might cause the pilot to maneuver considerably to land and to have the parameters of the descending rate and the approach speed exceeding the company's stable approach standard, which exists a contradiction

between the training manual and the FOM. When the aircraft was approaching Si-Cang VOR radio station, Pilot Flying (PF) was performed by the F/O. The captain as Pilot Monitoring (PM) without asking PF's approval, decided himself to assist the PF to adjust the course from 125 to 120 degree. As the FOM did not define the take-over timing, the two pilots did not determine the time to transfer duties though both pilots had decided to have the captain

NARRATIVE

as PF during landing. The captain took over when the aircraft was at 1.5 nautical miles from the runway 18R threshold. When the captain disengaged the auto-pilot, he was on duty as PM before using the standard call-out or any other ways to take over and did not call out 'auto-pilot disengage' to disengage the auto-pilot by himself. The F/O as PM during the final approach phase did not perform the standard call-out procedure per manual. When the ATC controller reminded that '642, the runway you are aiming is wrong', the captain, then already as PF, took the initiative to respond with the microphone 'runway in sight'. However according to the procedures the radio communication shall be the responsibility of PM performed by the F/O. There existed a condition of hierarchy between the two pilots. It may not be excluded that this factor affected the performance during the occurrence. Encountering the pressure that the captain did not follow the procedures to disengage the auto-pilot and took over the command and that the aircraft had

an approach during heavy rain, the F/O could not keep calm and had the symptoms of having pressure, such as nervousness and failing to handle the sudden events, which made him unable to fulfill effectively the duty as a PM during visual descent at the approach phase. For the captain, he should have worn glasses to rectify his far sighted vision for both eyes and the near sighted vision for the left eye but failed to follow the requirement to wear glasses according to the limitation stated in his medical certificate. Safety Recommendations: To Uni Air : Reinforce to request Dash-8 pilots to follow FOM's standard operation procedures, for example, the transfer of the command and the regulations to the approach visual reference. Reinforce crew resources management trainings in flight crew communication, attention and response to stress. Review and consider to revise relevant contents of the Dash-8 flight crew training manual to meet the FOM's requirement of the stable approach, to add timing of the command transfer when the F/O encounters landing limitation in the FOM and the operation skill of the VOR approach at the runway 18L at Tainan Airport, to have a training plan of the Dash-8 simulator training to identify the runway during the non-precision approach at parallel runways and to emphasize reminders related to identifying

landing runways. Request pilots to perform flight duties following the requirement from the limitation defined in the medical certificate accordingly; with the compulsory reporting of flight safety related events defined in the 'Regulations for Aircraft Flight Safety-related Events', supervise flight crew to follow the 'Aircraft Flight Operation Regulations' Article 111 and the FOM regulations that flight crew shall deactivate the CVR immediately after suspecting any occurrence of the flight safety related events. Revise the operating skill related to the non-precision approach in the FOM to request each

aircraft type to employ the operating skill of without descend final approach when non-precision approach is performed, and reinforce to request flight crew to follow the procedures of the stable approach to improve flight safety and to have daily self-inspections concerning flight operation. To CAA: Evaluate cautiously the possibilities to set up navigation facilities such as additional instrument landing systems or Localizer stations to assist aiming to runways with better accuracy and promulgate appropriate instrument approach procedures. Issue additional warning notifications for NDB and VOR

NARRATIVE

instrument approach chart at Tainan Airport to raise the alert of identifying runways to remind pilots to pay attention. Supervise Uni Air to request Dash-8 pilots to follow FOM standard operation procedures, for example, the transfer of the command and the regulations to the approach visual reference. Reinforce crew resources management training of the flight crew communication, the attention and the stress management. Review and consider to revise the FOM's content related to the stable approach to meet the actual requirement of the Dash-8 aircraft type, to add timing of the command transfer when the F/O encounters landing limitation. Review and consider to add the operation skill related to the non-precision approach procedures, the simulator training to identify the landing runway at parallel runways and verifying reminders of the landing runways. Implement the CVR deactivation procedures after the occurrence of flight safety related events. Refer to ICAO to promote continuous descend final approach, to reinforce trainings of the flight operation inspectors and relevant staff and to revise relevant manuals, procedures and the approach chart. To Air Force Command

Headquarters: Supervise Air Force Meteorological Wing to establish reporting operation procedures concerning any significant alternations to the installation, the cancelation and the booking of the weather equipment and the revision of the weather information to ensure that all relevant units and departments promptly receive the notifications.

EVENTS

Wrong runway selected , during Final approach. {Occurrence}

VOR : Lack of precision

Cumulonimbus : Low level; Adversely affected

Rain : Heavy; Adversely affected

Windshield wiper system (ATA Code:3043) : Not used

Aerodrome/heliport approach lighting : Not observed

Flight crew's decision about an approach : Improper

Flight crew., Human knowledge acquisition factors situational awareness : Insufficient

Runway incursion by an aircraft , during Landing. {Occurrence}

Flight crew's decision to land : Improper

Pilot., Workload task demands : High

Pilot., Psychological-fascination/fixation/channelized attention

Co-pilot., Human interface-Standard Operating Procedures : Not followed

Flight crew., The interface between humans in relation to team skills crew/team resource management training : Improper

WEATHER

General weather conditions

Weather conditions	VMC	Light conditions	Daylight
Weather relevant	Yes	Wind speed	13 kt
Speed measured at	Surface	Visibility	2400 m

Clouds

Cloud amount	Few clouds (1/8-2/8)	Height of cloud base	300 ft
---------------------	----------------------	-----------------------------	--------

Temperature

Air temperature	24 C	Dew point	24 C
------------------------	------	------------------	------

Precipitation and other weather phenomena

Precipitation intensity	Moderate	Precipitation type	Rain	Characteristics
--------------------------------	----------	---------------------------	------	------------------------

Weather reports

METAR	Report validity	Content wx report
	Valid	

DE HAVILLAND - DHC8-300, B-15231**Aircraft identification**

Manufacturer/model	DE HAVILLAND - DHC8-300	State of registry	Taiwan Island
Year built	1995	Aircraft registration	B-15231
Aircraft serial number	414	Call sign	GLORY
		Flight number	B7642

Aircraft Operation

Operator	Taiwan - Uni Air - (to be coded)	Operation type	Commercial Air Transport - Scheduled revenue ops - Domestic - Passenger
Operator type		ICAO information	

Aircraft description

Aircraft category	Fixed wing	Wake turb. category	Medium
Propulsion type	Turboprop	Mass group	5 701 to 27 000 Kg
Number of engines	2	Maximum take-off mass	19504.473 kg
Landing gear type	Tricycle, retractable	GNSS installed	
EFIS	Yes, partial		

Aircraft status

Total cycles a/c	54509	Maintenance docs.	Current
Aircraft total time	28979.25 Hour(s)	Airworthiness cert.	Valid

Fuel

Fuel type used	Turbine engine fuel - Jet A-1 (F35 NATO)	Recommended fuel type
Fuel quantity on board		

HISTORY OF FLIGHT**Itinerary**

Last departure point	Taiwan - RCQC (MZG): Magong Airport - (to be coded)	Flight phase	Landing
Planned destination	Taiwan - RCNN (TNN): Tainan Airport - (to be coded)	Duration of flight	19 Minute(s)
		Occ. on ground	Yes

Landing

Type of landing	Regular landing	Automatic landing	No
Electronic landing aids	VOR DME	Landing location.	On land/on aerodrome

Approach

Visual approach type		A/c app for prec app	
VASI used	None	Precision app. cat.	
Approach RVR status	Above minima	Instr. approach type	VOR/DME
Approach stabilized		Approach errors	Other
Instr. landing proc.			

Person at controls

Person at controls	Pilot-in-command
---------------------------	------------------

INJURIES**Injuries**

	Fatal	Serious	Minor	None	Unknown	Total
Pilot	0	0	0	1	0	1
Co-pilot	0	0	0	1	0	1
Cabin crew	0	0	0	2	0	2
Other flight crew	0	0	0	0	0	0
Crew Total	0	0	0	4	0	4
Passengers	0	0	0	43	0	43
Other on Aircraft	0	0	0	0	0	0
Unknown	0	0	0	0	0	0
Total	0	0	0	47	0	47

Injury types

	Fatal injuries	Non-fatal injuries	Unknown
Burns	0	0	0
Drowning	0	0	0
Fumes/gases	0	0	0
Impact	0	0	0
Shock exposure	0	0	0
Other reasons	0	0	0
Unknown	0	0	0

Autopsy

Persons autopsied	None
--------------------------	------

AIRCRAFT RECORDINGS**Cockpit voice recorder**

CVR location	Rear fuselage	CVR recovery	Recovered
CVR Recording medium	Solid state	Underwater locator (CVR)	
Number of channels	4	CVR Reason for data loss	Other
CVR Recording duration	30 Minute(s)	CVR Recording quality	Good
Hot microphone	yes		

Flight data recorder

FDR location	Rear fuselage	FDR recovery	Recovered
FDR Recording medium	Solid state	Underwater locator (FDR)	
Number of parameters	107	Reason for data loss	
FDR Recorder type	Digital FDR	FDR data recovery	Completely recovered
		FDR Data usefulness	Useful

AIR TRAFFIC SERVICES**Flight plan**

Filed flight rules		Current flight rules	VFR
Filed traffic type		Current traffic type	
Flight plan type		SSR code	
		SSR mode	

Flight level, altitude

	Height	Altimeter (QFE)	Altitude	Altimeter (QNH)	Flight level
Actual				1030 hPa	
Cleared					
Requested					
Co-ordinated entry					
Co-ordinated exit					

FLIGHT CREW**PILOT-IN-COMMAND****Flight crew member**

Age	62 Year(s)	Category	Pilot-in-command
Gender - Crew Member	Male		

Flight crew rest/duty

Duty last 24 hours	0.92 Hour(s)	Rest before duty	10 Hour(s)
---------------------------	--------------	-------------------------	------------

Flight crew experience

	Last 24 hours	Last 90 days	Total
This Aircraft type	0.92 Hour(s)	203 Hour(s)	14022 Hour(s)
All types	0.92 Hour(s)	203 Hour(s)	17873 Hour(s)

Flight crew licences

License type	Ratings	Validity	Registry State issued	Instructor rating	Instrument rating
Aeroplane pilot - Airline transport pilot	Held required rating	Valid, medical waivers	Yes	No	Yes

CO-PILOT**Flight crew member**

Age	37 Year(s)	Category	Co-pilot
Gender - Crew Member	Male		

Flight crew rest/duty

Duty last 24 hours	0.92 Hour(s)	Rest before duty	10 Hour(s)
--------------------	--------------	------------------	------------

Flight crew experience

	Last 24 hours	Last 90 days	Total
This Aircraft type	0.92 Hour(s)	183 Hour(s)	2302 Hour(s)
All types	0.92 Hour(s)	183 Hour(s)	693 Hour(s)

Flight crew licences

License type	Ratings	Validity	Registry State issued	Instructor rating	Instrument rating
Aeroplane pilot - Airline transport pilot	Held required rating	Valid, no waivers	Yes	No	Yes

AERODROME**Aerodrome identification**

Aerodrome type	Land	Aerodrome latitude	22:57 North
Location indicator	Taiwan - RCNN (TNN): Tainan Airport - (to be coded)	Aerodrome longitude	120:13 East
Aerodrome status	Public aerodrome	Elevation above MSL	64 ft

RECOMMENDATIONS**Recommendations**

Recommendations	Personnel - Training Procedures - Study/review Personnel - Proficiency check Personnel - Other Other - Aerodrome facilities Procedures - Compliance
-----------------	--

MANAGEMENT**Occurrence report**

Report identification	B7642	Report last modified	2014/7/9 PM 04:33:59
Report moderator		Report status	Data
Report source	Accident/Incident investigation	Reporting form type	ICAO - Final Report
Date report created	2012/10/16 PM 12:21:01		