

Case of Freight Train Derailment on a 153 m Radius Turnout


October 23, 2025

Injae Kim (Investigator, Ph.D, PE)



Ministry of Land,
Infrastructure and Transport

Aviation and Railway Accident Investigation Board (ARAIB)



CONTENTS

- I Introduction
- II Cause of freight train derailment on a 153m radius turnout
- III Accident prevention
- IV Conclusion(How can we make a railway safer?)

I | Introduction

● Myself

- ▶ My name : Injae Kim (e-mail : injaero1@korea.kr)
- ▶ Licensed : PE and Ph.D (Civil)
- ▶ My career

Duration	Workplace	Position	Remarks
2022.10.17–Present	ARAIB	Investigator	Public
2018.12.1–2022. 10. 17	Western Metro co., Ltd	Director	Private
2015.12.1–2018. 11. 30	ARAIB	Investigator	Public
1992.4.29–2014. 12. 10	Korea Rail Network Authority	Leader of the team	Public
1983.12.23–1992. 4. 28	Office of Railroads	Staff	Public

- ▶ Main Projects
 - Gyeongbu and Honam High Speed Railway Line
 - **Daegok**-Sosa Line (BTL)


I | Introduction

● Organization

- ✓ Name : "Aviation and Railway Accident Investigation Board (ARAIB)"

<http://www.araib.go.kr>

- ✓ Establishment : July, 2006



● Scope of Railway Accident Investigation

- ▶ Train collision or derailment



- ▶ Fire on rolling stock or a train that halts an operation

- ▶ 3 or more casualties concerning rolling stock or a train operation

- ▶ 50 million won or more property damage regarding rolling stock or a train operation

I Introduction

Annual Railway Accident Statistics




✓ For 11 years, there have been an average of 6.1 accidents annually.


II Cause of freight train derailment on a 153 m radius turnout

1 Overview of the accident


- ✓ Date and time of accident : Sunday, August 18, 2024, at 16:32
- ✓ Accident type : Freight train derailment




II Cause of freight train derailment on a 153 m radius turnout




II Cause of freight train derailment on a 153 m radius turnout




II Cause of freight train derailment on a 153 m radius turnout



II Cause of freight train derailment on a 153 m radius turnout



II Cause of freight train derailment on a 153m radius turnout



- ✓ Damage: The vehicles, track, and signal were damaged

II Cause of freight train derailment on a 153 m radius turnout

2 Consideration of the causes of derailment


- Review of technical specifications for vehicle manufacturing
- ✓ Operational safety requirements under **the railway vehicle technical standards**

The derailment coefficient in a rail section with 250 m or more curve radius is defined as follows: ① when the probability of occurrence for one vehicle reaches **100%, values up to 0.8** are permissible, ② For a probability of **0.1%, values up to 1.1** are permissible, ③ The **maximum allowable value is 1.2**

- ✓ **Track conditions** to be considered in vehicle design

- ① Track gauge : 1,435 mm
- ② Maximum gradient : 35 ‰
- ③ Minimum curve radius in operation : **250 m**

II Cause of freight train derailment on a 153 m radius turnout



II Cause of freight train derailment on a 153 m radius turnout


✓ The railway vehicle technical standards

When the **flange angle** is taken as $\alpha=60^\circ$ and the friction coefficient $\mu=0.3$ is applied to the formula, the derailment coefficient becomes **0.94**. Applying a safety factor $k=0.85$, the calculated value becomes 0.8. Thus, the standard is **0.8**.

✓ The derailment coefficient of the EN14363


Classification	Derailment coefficient	Remarks
General case	0.8	
Wheel rise 5 mm within a curve radius of 150 m, When friction coefficient 0.4 and flange angle 70°	1.1	
When friction coefficient 0.36 and flange angle 70°	1.2	

II Cause of freight train derailment on a 153 m radius turnout




$$L = N \sin \alpha - T_Y \cos \alpha$$
$$V = N \cos \alpha + T_Y \sin \alpha \quad T_Y \leq \mu N$$

II Cause of freight train derailment on a 153 m radius turnout




II Cause of freight train derailment on a 153 m radius turnout

- ✓ JR EAST Technical Review-No.30 "A Study on the Prevention of Wheel-Climb Derailment at Low Speed Ranges"



II Cause of freight train derailment on a 153 m radius turnout



II Cause of freight train derailment on a 153 m radius turnout


- Limit derailment coefficient considering equivalent friction coefficient

Classification/curve radius		250 m	200 m	150 m	120 m	100 m (including F8 turnout)
Attack angle (°)			0.6	0.8	1.0	1.2
Equivalent friction coefficient		0.3	0.33	0.40	0.42	0.44
Derailment coefficient	Flange angle 60° () values consider a safety factor of 0.85	0.94 (0.80)	0.89 (0.76)	0.79 (0.67)	0.76 (0.65)	0.73 (0.62)
	Flange angle 65° () values consider a safety factor of 0.85	1.12 (0.95)	1.06 (0.9)	0.94 (0.8)	0.91 (0.77)	0.88 (0.75)
	Flange angle 70° () values consider a safety factor of 0.85	1.34 (1.14)	1.27 (1.08)	1.12 (0.95)	1.08 (0.92)	1.04 (0.88)


II Cause of freight train derailment on a 153 m radius turnout

3 Safety assessment of a 3-axe bogie on sharp curves


● Track Measurement Results



III




II Cause of freight train derailment on a 153 m radius turnout




II Cause of freight train derailment on a 153 m radius turnout

● Locomotive structure



II Cause of freight train derailment on a 153 m radius turnout

Lateral displacement between axle and bogie frame : 12mm



Bogie frame

Primary suspension spring

II Cause of freight train derailment on a 153 m radius turnout

● Clearance between the inner wheel and rail of the 2axle (δ_{2u})

$$\delta_{2u} > 0$$

$$\delta_{2u} (R: 151) = \delta - f - 0.5 \times \delta_s = 28.5 - 15 - 0.5 \times 25 = 0.5 \text{ mm}$$

δ_{2u} : Clearance between the inner wheel and rail of the 2axle

δ : Lateral clearance between wheel and rail


f : Clearance between the outer wheel and rail of the 2axle

δ_s : Clearance between the flange of the outer wheel and the outer rail(max 25mm) of the 3axle

$$\delta_{2u} (R: 151) = 0.5 \text{ mm} > 0$$


※ Assessment of derailment influence from increased friction caused by wheel grinding day before the accident

II




II Cause of freight train derailment on a 153 m radius turnout

- 4** The specified distance ≥ 5 m between turnouts does not comply with the Railway Design Manual.




II Cause of freight train derailment on a 153 m radius turnout

Current status



Regulation



II Cause of freight train derailment on a 153 m radius turnout

5 The primary cause of the derailment

- ✓ **The cause of the freight train derailment:** "excessive lateral force exerted on the three-axle bogie while negotiating a turnout with a radius significantly tighter (153 m) than the vehicle's specified minimum curve radius (250 m)."
- ✓ **The contributing factor:** The locomotive was manufactured according to the manufacturer's specification requiring a minimum curve radius of 250 m, but was operated on track sections with a curve radius of 153 m.

II Cause of freight train derailment on a 153 m radius turnout

6 Safety recommendations

- ✓ Review and, if necessary, revise the derailment coefficient criteria prescribed in the Railway Vehicle Technical Standards to ensure they reflect appropriate vehicle and track interaction limits.
- ✓ Develop measures for operating trains on turnouts with radii smaller than those permitted by the rolling stock's technical specifications, as such non-compliance increases derailment risk.
- ✓ Improvement measures shall be implemented at locations where the turnout spacing specified in the Railway Design Manual is insufficient.

III | Accident Prevention

1 Accident prevention activities

- ✓ Proper design and construction of the railway
- ✓ Regular track inspection and maintenance
- ✓ Rolling stock safety checks
- ✓ Signal and communication system monitoring
- ✓ Safety training and awareness programs for the employees
- ✓ Implementation of advanced safety technologies
- ✓ Emergency preparedness and response drills

2 Expected improvements

- ✓ Enhanced operational safety
- ✓ Reduction of accidents and incidents
- ✓ Increased reliability of railway services
- ✓ Improved passenger and worker confidence
- ✓ Cost reduction from fewer disruptions
- ✓ Stronger safety culture across the organization

IV Conclusion(How can we make a railway safer?)

- ✓ Establishment Railway Safety Management System(2004)
 - Introduction of the **SMS**(Safety Management System)
 - Introduction of the RAMS(Reliability, Availability, Maintainability, Safety) technique
 - Introduction of the System Engineering

+

- ✓ Measures of the accident prevention
 - Vehicle improvement
 - Facility improvement
 - Strengthening of employee education and training
 - System improvement
 - Research and development
 - Risk assessment

IV Conclusion (How can we make a railway safer?)

- ✓ Make a good facility
- ✓ Suitable law, rule, manual
- ✓ Well-trained worker
- ✓ Continuous research and development



Ministry of Land,
Infrastructure and Transport

Thank you.



Aviation and Railway Accident Investigation Board (ARAIB)