



Passenger Train Derailment on Pingxi Branch Line

Jackie Chen
2025.10.23

Contents



- Accident
- Findings
- Recommendations

Accident


On February 12, 2024, Taiwan Railways Corporation, Ltd. (TRC) local train No. 4816, consisting of four cars, experienced a derailment after departing Lingjiao Station on the Pingxi Branch Line. The first and second axles at the front end of car No. 3 derailed.



Accident Scene




Left




Right


Track




Gauge





Cant





Static Twist



Dynamic Twist




Ballast




Lacer Scan


**Point of
mount**




**First bogie of
the derailed car**



ATP Record




Car Level




Left – Right Difference	Diagonal Difference
$ \#1 - \#2 $ 30 mm	$ \#2 - \#4 $ 60 mm
$ \#3 - \#4 $ 20 mm	$ \#1 - \#3 $ 110 mm
< 10mm	< 20mm

Static Wheel Load Ratio



$$\left| 1 - \frac{\text{Single wheel load}}{\text{Average wheel load of both wheels}} \right| \times 100\%$$



Wheel Load Change Ratio



Leveling Valve









Leveling Valve Failure Analysis


Inflate position

Normal

Exhaust position



Leveling Valve Failure Analysis




- Rust → Chips → Piston stuck → Leveling valve failure


Energy-dispersive X-ray Spectroscopy, EDS

- Chips contain non-metallic elements
 - C、O → Metal corrosion
 - Si → Silicon oil
 - Small amounts of corrosive element: S → From outside

Simpack Rail Simulation



Derailment Coefficient Threshold



Nadal Formula


$$\frac{L}{V} \geq \frac{\tan(\alpha) - \mu}{1 + \mu \tan(\alpha)}$$

L: Lateral force at wheel flange

V: Vertical load on the wheel

α: wheel flange angle at plane of contact

μ: Coefficient of friction at flange/rail contact point



Findings Related to Probable Causes

Malfunction of the air spring leveling valves (#1 & #3)



Poor track geometry (Twist)



No guard rail



The minimum derailment coefficient threshold dropped
below international safety standards

Findings Related to Risk

No guard rail

- Inconsistent installation criteria
 - Mainline track curve radius is less than 400 meters.
 - The line shall be designated for both passenger and freight operations, and classified as a commuter electrified railway corridor.
- The TRC's interpretation
- TRC also thought:
 - Train speed is low when arriving and departing Lingjiao Station.

Findings Related to Risk

Rolling Stock


- No wheel load management measures

Track

- Post-maintenance inspections are conducted only at isolated points
- No established time limits
- Ineffective drainage

Findings Related to Risk

- The TRC's inspection systems are **unable to detect** the reduction rate of **rail cross-sectional area**, from Category A inspections to routine track patrols.



- The Railway Bureau's periodic and non-periodic **inspection frequencies** on the Pingxi Branch Line were **insufficient** to identify this segment as high-risk promptly and to mandate corrective action from the TRC.

Safety Recommendations

To the Ministry of Transportation and Communication

- Review and revise the “Track Maintenance and Inspection Regulations for 1067 mm Gauge” to **clearly define the criteria for guard rail installation** and to **include standards for railhead wear**.

To the Railway Bureau

- Review and strengthen the **inspection mechanisms** for both track maintenance on the Pingxi Branch Line and maintenance practices of DRC1000 series rolling stock.

Safety Recommendations

To the Taiwan Railway Corporation, Ltd.

- Evaluate incorporating wheel load as a vehicle maintenance indicator and **establishing a wheel load management system.**
- Improve **drainage functionality** along the Pingxi Branch Line.
- Establish **repair deadlines** for rectifying track irregularities exceeding emergency maintenance thresholds and **reinforce post-maintenance inspection procedures.**
- Review and improve **rail wear inspection methods** to ensure compliance with regulatory standards.

Thank you for your attention



Executive Summary in English



Full report in
Traditional Chinese

國家運輸安全調查委員會
Taiwan Transportation Safety Board