重大公路事故調查初步報告

HIGHWAY OCCURRENCE PRELIMINARY REPORT

			WIINAKI KEFUKI				
檔案資訊 FILIN	NG INFORMATION						
標題簡述	1131117臺北市大有公車忠孝東路往東鎮江街口追撞大都會公車事故						
Headline	A CitiAir Bus rear-ended a Metropolitan Transport Bus at the intersection of Zhongxiao						
	East Road and Zhenjiang Street in Zhongzheng District, Taipei City						
報告國		最初登入報告					
State reporting	中華民國 Taiwan, ROC	日期	2024/11/18 13:33				
		Date entered					
報告檔案編號		報告機關	國家運輸安全調查委員會				
State file number	TTSB-HOD-24-11-001	Reporting org	Taiwan Transportation Safety Board (TTSB)				
報告代號		報告狀態	·/				
Report	N/A	Report status	初步報告 Preliminary				
identification			,				
報告者	兹 4 则 F _ 1 G'	<u> </u>	1				
Reporter's name	蕭牟淵 Frank Siao						
電話		電子郵件					
Telephone	+886-2-7727-6271	Email	frankbet@ttsb.gov.tw				
調查程度			1				
Scope of	完整 Full						
Investigation	/						
類別 CLASSIFI	ICATION						
20111			<u> </u>				
事故等級	4n Classi	事故分類	** 上工 / 古 · · · · · · · · · · · · · · · · · ·				
Occurrence class	一級 Class1	Occurrence	造成死傷事故 Cause death or injury.				
	<u> </u>	category	<u> </u>				
時間 WHEN		_					
當地時間	2024/11/17 09:05	世界標準時間	2024/11/17 01:05				
Local date	2027/11/17 07:03	UTC date	2027/11/1/ U1.UJ				
地點 WHERE							
事故發生國		事故發生縣市					
State of	中華民國 Taiwan, ROC	County or city	臺北市 Taipei City				
occurrence		of occurrence					
事故發生道路種							
類	本原送咖 II.L D 1						
Highway type of	市區道路 Urban Road						
occurrence							
事故發生位置	* 1 + 1 +	4 A	manufaction of COLOR 1 To 1 To 1				
Location of		臺北市中正區忠孝東路與鎮江街口 At the intersection of Zhongxiao East Road and					
occurrence	Zhenjiang Street in Zhongzheng District, Taipei City						
緯度							
Latitude Deg/	25 度(°) 02 分(')42.7 秒(")N						
Min/ Sec							
經度							
Longitude Deg/	121 度(°) 31 分(')17.2 秒(")E						
Min/ Sec							
嚴重程度 SEVE	ERITY						
車輛損害		傷亡等級	A 1				
Damage Vehicle	部分受損 Partial	Injury level	A1				
其他損害		, , , , , , , , , , , , , , , , , , , ,	•				
Third party	是,本次事故造成3輛車輛受持	員 Yes., this occur	rence causes damage to 3 vehicles.				
damage	一	,,, and occur	James to 5 venicies.				
uamage	L						

傷亡總數 INJURY TOTALS								
	死亡 Fatal	受傷 Injury	無傷 None	未知 Unknown	小計 Total			
駕駛員 Drivers	0	1	0	0	1			
乘客 Passengers	0	14	0	0	14			
行人 Pedestrians	1	0	0	0	1			
其他 Other	0	0	0	0	0			
未知 Unknown	0	0	0	0	0			
總計 Total	1	15	0	0	16			

一般天氣 GENERAL WEATHER CONDITIONS						
天氣條件 Weather conditions	晴天 Sunny	光線 Light conditions	白天 Daylight			
運行經過 HISTORY OF OPERATION						
起點 Departure point	臺北市南港區 Nangang District, Taipei City	運行狀態 Operation phase	運行中 Operating			
預計終點 Planned destination	臺北市萬華區 Wanhua District, Taipei City	運行時間 Duration of Operation	1時10分 1 hour 10 minutes			

簡述 NARRATIVE

民國 113 年 11 月 17 日 9 時 5 分,1 輛大有巴士股份有限公司所屬公車於臺北市中正區忠孝東路與鎮江街口,追撞 1 輛停讓行人之大都會汽車客運股份有限公司所屬公車後,繼續推撞 1 名行人及 1 輛計程車,造成 1 人死亡、15 人受傷。

On November 17, 2024, at 9:05 A.M., a bus operated by CitiAir Bus Co. rear-ended another bus operated by Metropolitan Transport Co., which was giving way to pedestrians. The bus in the front struck a pedestrian and another taxi at the intersection of Zhongxiao East Road and Zhenjiang Street in Zhongzheng District, Taipei City. As a result of the crash, a pedestrian was fatally injured, and another 15 passengers sustained injuries.

註 1:N/A 表不適用或於現階段無資料